


Illustrates: Suspension parallel to truss system with added ST-1 cross steel bolted to top flange. CL-5 unit clamp bolted through center space of the ST-1.



Note: Structural Strength of Truss & Wall NOT Responsibility of Mat Hoist Manufacturer.

NGE Inc.  
P.O. Box 370/Industrial Park  
302 North Erickson  
Roland, IA 50236

Mat Hoist 1000  
ST-1 Spanning Truss  
Drawing MH1000-09

Phone: (515)-388-4118  
Fax: (515) 388-4340  
Email: mathoist@mathoist.com  
Website: www.mathoist.com