


Illustrates: Suspension parallel to truss system with added ST-1 cross steel bolted to top flange. CL-5 unit clamp bolted through center space of the ST-1.



Note: Structural Strength of Truss & Wall NOT Responsibility of Mat Hoist Manufacturer.

NGE Inc.
P.O. Box 370/Industrial Park
302 North Erickson
Roland, IA 50236

Mat Hoist 1000
ST-1 Spanning Truss
Drawing MH1000-09

Phone: (515)-388-4118
Fax: (515) 388-4340
Email: mathoist@mathoist.com
Website: www.mathoist.com